



## Invoice I080975

Date: 16-10-2023 2:02 PM  
 Technician: Kevin Taylor  
 Estimate: Q032313  
 Job: J081439

**Vehicle** Registration: OV16YVM Mileage: 65342  
 Land Rover Discovery Sport 2016 2.0 Diesel - RED VIN: SALCA2AN1GH618271

### Work performed

#### Labour

Labour	VAT %	Net Total
Replace timing chain	20.0	1,020.00
oil and filter change	20.0	42.50

Parts	Part No	Qty	Unit Price	VAT %	Net Total
Environmental Charge	ENVIRO	1.00	2.00	20.0	2.00
Engine Flush	FORTEEF	1.00	9.95	20.0	9.95
fuel cleaner	FORTEFC	1.00	9.95	20.0	9.95
tool hire	GENUINE	1.00	50.00	20.0	50.00
tensioner	LLR084294	1.00	92.94	20.0	92.94
timing chain guide	LLR073756	1.00	26.70	20.0	26.70
plug	LLR073789	1.00	2.59	20.0	2.59
crankshaft seal	LLR084639	1.00	31.67	20.0	31.67
tensioner	LLR138833	1.00	79.53	20.0	79.53
sealing ring	LLR073794	1.00	17.68	20.0	17.68
arm	LLR073761	1.00	25.36	20.0	25.36
timing chain	LLR132676	1.00	62.49	20.0	62.49
guide	LLR073755	1.00	27.03	20.0	27.03
arm	LLR124262	1.00	27.60	20.0	27.60
chain	LLR13320	1.00	72.83	20.0	72.83
guide	LLR120540	1.00	32.55	20.0	32.55
gasket	LLR073816	1.00	20.54	20.0	20.54
idler	LLR124261	1.00	46.46	20.0	46.46
plug	LLR073675	1.00	5.61	20.0	5.61
oil filter	LLR073669	1.00	15.24	20.0	15.24
sealer	LSTC50550	1.00	14.46	20.0	14.46
FD OW-30 ECO LS (1L)	NPAN2291L	6.52	12.01	20.0	78.31
bolt	LLR074135	8.00	1.31	20.0	10.48
Engine coolant	GEC5001B	2.50	4.67	20.0	11.68

**Labour SubTotal £1,836.15**

### Invoice Total

VAT Code	Rate %	Net Total	VAT Total
(1)	20.00	1,836.15	367.25

Labour	1,062.50
Parts	773.65
VAT	367.25

**Invoice Total £2,203.40**

