

Issued by John Bartlett's Garage & ESVAC EASTBOURNE

RIZ
Santa Cruz Drive
Eastbourne
East Sussex
BN23 5TA

Invoice Number: **3548**
Account Number: RIZ-119
Order Ref / Number: PT
Invoice Date: 07/09/2015
Payment Method: PENDING
Date of Work: 07/09/2015

Registration	Make & Model	Chassis Number	Engine CC	Mileage
GY55UBB	MAZDA 2	JMZNEAWPJN5P07033	1.4 TDI	57377

REPLACE CAM BELT & WATER PUMP.

Labour Description	Qty / Hrs	Unit Price	Price
SUPPLIED & FITTED NEW CAM BELT & TENSIONERS	2	50.00 Less 10%	90.00
SUPPLIED & FITTED NEW ALTERNATOR BELT			
Labour Sub Total			90.00

Parts Description	Part No	Qty	Unit Price	Price
CAM BELT KIT	CMB	1	79.95 Less 10%	71.96
WATER PUMP AND SEAL or GASKET	W/P	1	36.50 Less 10%	32.85
ANTI FREEZE RED	AFR	2	3.00	6.00
ENVIRONMENTAL CHARGE	EV	1	2.50	2.50
SERVICE SUNDRIES	S/S	1	4.00	4.00
ALTERNATOR BELT	ALB	1	22.95 Less 10%	20.66
Parts Sub Total			137.97	

LABOUR & PARTS	227.97
VAT at 20%	45.59
TOTAL DUE	273.56

Important Information / Advisory Notices

RECOMMENDED CAM BELT REPLACEMENT 150000 MILES OR 10 YEARS.

PAID ON 7.9.15.